


**Slim, 3,000 Amp**  
**Flexible current probe**  
**Flexible clamp meter**



**FLEXIBLE CLAMP METER**

**Model : CMF-6130**

- \* Flexible clamp meter, complete set with meter and separate slim flexible clamp probe, easy and convenient to measure the ACA up to 3000 A ( auto range ). The meter also has more other features available for the ACV. DCV, ohm, capacity, diode, continuity, Hz... measurement.
- \* Flexible probe length : 600 mm ( 23.6 inch ). Flexible probe diameter : 8 mm.
- \* AC 3000A : auto range.
- \* V : ACV, DCV, Hz measurement automatically.
- \* Ω: Ohm, Diode, Continuity, Capacitance automatically.
- \* Function slide switch : AC 3000A/ohm/V
- \* Push button Keys : Hold, Select, Hz , Range.
- \* Large LCD display, 6,000 counts.
- \* CAT III 600V, Auto power off.
- \* Power : DC 9V battery ( 006 P ).
- \* Size : 151 x 78 x 43 mm.
- \* Complete set with Flexible clamp probe, meter, test leads and soft carrying case.



**Slim Flexible current probe, 3000 Amp**

**Model : CPS-3100**

- \* Range : 30 A/300 A/3000 A.
- \* Output sensitivity : 100 mV/A, 10 mV/A, 1 mV/A.
- \* Output voltage : 3 ACV ( 30 A, 300 A, 3000 A ).
- \* Flexible probe length : 600 mm ( 23.6 inch ). Flexible probe diameter : 8 mm.
- \* When changing the new probe, the calibration procedures are not necessary to be executed.
- \* Output cable : 2 cables ( 4 meters in length ), use the banana plugs, durable and safety.
- \* Power supply : DC 1.5V battery ( UM-3/AA ) x 2 PCs or DC 9V adapter in. AC to DC 9V adapter is optional.
- \* CPS-3100 can cooperate any kind DMM ( ACmV meters ), if those meters are built-in the ACV mV measurement range to be used as the AC 3000 Amps ( max. ) current meter.